

1. Serial number and rating plate information

The serial number, tool type designation and generation number are of great importance for the efficient, unequivocal identification of Hilti tools or appliances.

The information below is intended to explain each of the numbers or designations (Section 2) and indicate the exact location of this information on the tool or appliance (Section 3).

2. Explanation of rating plate information

The rating plates are of a uniform design and in a gray color (when positioned on a red housing) and in black (when on a black housing).

The serial number is normally located on the rating plate (fig. 1). In cases where the serial number is engraved on the housing, this is indicated by the comment "see housing" on the rating plate (fig. 2).




Fig. 1: Rating plate showing serial number





Fig. 2: Example of a rating plate where the serial number is engraved on the housing.

3. Overview Tools



3.1 Sanders

WFE 150 R 	WFE 380 R 	WFE 450-E R
WFO 280 R 		

3.2 Saws

WSC 6.5 / WSC 7.25-A R 	WSC 7.25-S R 	WSC 55_01 R
WSC 55_02 R 	WSC 55-A / WSC 70-A R 	WSC 70_02 R

WSC 85 R 	WSC 155 R 	WSC 255 / WSC 255-KE R 
WSC 265 / WSC 365-KE R 	WSC 267-E R 	WSJ 110-EB R 
WSJ 110-ET R 	WSJ 750-EB R 	WSJ 750-ET R 
WSJ 850-EB R 	WSR 650-A R 	WSR 22-A/WSR 18-A R 
WSR 36-A R 	WSJ 580-ET R 	WSR 900 R 

WSR 900-PE <i>R</i> 	WSR 1000 <i>H</i> 	WSR 1200-PE <i>R</i>
WSR 1250-PE <i>R</i> 	WSR 1400-PE <i>R</i> 	

3.3 Screw drivers and drills

SD 2500 <i>H</i> 	SD 4500 <i>R</i> 	SD 45 <i>H</i>
SD 5000 <i>R</i> 	SD 5000-A22/SD 4500-A18R 	SDT 25 / SDT 25-15 No serial number tracking
SF 4000 <i>H</i> 	SI 100 <i>R</i> 	SMI 55 plus <i>H</i> No rating plate

SR 16 H 	ST 18 H 	ST 1800 H
ST 2500 H 	SU 25 H 	TAD 500 H
TKI 2500 R 	SMD 57 No serial number	

3.4 Battery screw drivers

SF 100-A H 	SF 120-A H 	SF 121-A H
SF 144-A / SFH 144-A H 	SF 150-A H 	SF 151-A / SFH 151-A H

SF 180-A <i>H</i> 	SF 181-A / SFH 181-A <i>H</i> 	XBT 4000-A <i>H</i> 
SID 121-A / SIW 121-A <i>H</i> 	SID 144-A / SIW 144-A <i>H</i> 	TCI 12 <i>R</i> 
SF 18-A/SFH 18-A <i>H</i> 	SF 22-A/SFH 22-A <i>H</i> 	SFL 144-A 

3.5 Batteries and chargers

<i>R</i> B 24 3.0 NiCd 	B 36 2.4 NiCd <i>R</i> 	<i>R</i> B 36 3.3 Li-Ion 
<i>R</i> B 144 2.6 Li-Ion 	BP 10 <i>R</i> 	BP 12 <i>R</i> 

BP 40 <i>R</i> 	BP 6-86 <i>R</i> 	BP 60 <i>R</i> 
BP 72 <i>R</i> 	SBP 10 <i>H</i> 	SBP 12 <i>H</i> 
SFB 105 <i>H</i> 	SFB 125 <i>H</i> 	SFB 126 <i>H</i> 
SFB 150 <i>H</i> 	SFB 155 (3.0) <i>H</i> 	SFB 180 (NiCd) <i>H</i> 
SFB 185 (NiMH) <i>H</i> 	B 36 3.0 Li-Ion <i>R</i> 	BAP_TE 6-A <i>R</i>  No serial number tracking

Rating plate

Author: RTOscm, RTEhl | Issued: Jan 2012 | P 8 of 25

CU 10 <i>R</i> 		
C 4¹/₃₆ Li-Ion (family) <i>H</i> 	C 7¹/₂₄ / C 7¹/₃₆-ACS <i>H</i> 	SFC 7¹/₁₈ <i>H</i> 
SFC 7¹/₁₈H <i>H</i> 	TCU 24h <i>R</i> 	TCU 7¹/₃₆ <i>H</i> 
PRA 84 Li-Ion <i>R</i> 	B 36 2.6 Li-Ion <i>R</i> 	PRA 85_01 <i>R</i> 

3.6 Dispensers

BD 2000 <i>R</i> 	ED 3500 <i>R</i> 	ED 3500-A <i>H</i>
CA 301 <i>R</i> 	CB 100-P1 No serial number tracking	CB 120-P1 No serial number tracking
CF 130-P2 No serial number tracking	MD 1000 No serial number	MD 2000 No serial number
MD 2500 No serial number	HIT-P 2000 <i>R</i> 	HIT-P 3000 <i>R</i>
HIT-P 3500 <i>R</i> 	HIT-P 5000 <i>R</i> 	HIT-P 8000 D <i>R</i>

MD 300  No serial number tracking		
---	--	--

3.7 Measuring systems

FS 10 <i>R</i> 	PM 22 <i>R</i> 	PM 24 <i>R</i> 
PMA 30 <i>R</i> 	PMC 36 <i>R</i> 	PML 32 <i>R</i> 
PML 32 / PML 32-R <i>R</i> 	PMP 32 <i>R</i> 	PMP 34 / PMP 34-F <i>R</i> 
PR 16 <i>R</i> 	PR 20/25 <i>R</i> 	PR 28 <i>R</i> 

PRA 20 R  	PRA 25 R  	PRI 2 R  
PD 4 R  	PD 22 / PD 28 R  	PD 30 / PD 32 R  
PD 38 R  	PD 40 / PD 42 R  	PS 20 R  
PS 200 R   	PS 200 M / S R   	PX 10 R / PX 10 T R   
PA 350 R  	PS 35 R  	PP 10 R  

PRA 30 <i>R</i> 	PRE 3 <i>R</i> 	PMC 46 <i>R</i> 
--	---	--

3.8 Rotary Hammer

TE 1_01 <i>R</i> 	TE 1_02 <i>H</i> 	TE SX <i>R</i> 
TE 2_01 <i>H</i> 	TE 2_02 <i>H</i> 	TE 2-A_01 <i>H</i> 
TE 2-A22_02 TE 2-A18_02 		
TE 2-E_01 <i>H</i> 	TE 2-E_02 <i>H</i> 	TE 2-M_01 <i>H</i> 

TE 2-M_02 <i>H</i> 	TE 2-S_01 <i>H</i> 	TE 2-S_02 <i>H</i> 
TE 5 <i>H</i> 	TE 5-A <i>R</i> 	TE 6-A_01 <i>H</i> 
TE 6-A_02 <i>H</i> 	TE 6-C <i>H</i> 	TE 6-S <i>H</i> 
TE 4-A22_01 TE 4-A18_01 <i>H</i> 	TE 6-A36-AVR_03 <i>H</i> 	TE DRS-6-A_01 
TE 7_02 <i>H</i> 		

TE 7-A <i>H</i> 	TE 7-C <i>H</i> 	TE 15 <i>H</i>
TE 15-C <i>H</i> 	TE 16 <i>H</i> 	TE 16-C <i>H</i>
TE 16-M <i>H</i> 	TE 18-M <i>H</i> 	TE 24 <i>H</i>
TE 25 <i>H</i> 	TE 25-S <i>H</i> 	UD 16 <i>R</i>
UD 30 <i>R</i> 	UH 650 <i>R</i> 	UH 700 <i>R</i>

3.9 Combi Hammer

TE 30/ TE 30-AVR <i>H</i> 	TE 30-C-AVR <i>H</i> 	TE 30-M-AVR <i>H</i> 
TE 35 / TE 35-C <i>H</i> 	TE 40 / TE 40-AVR <i>H</i> 	TE 46 / TE 46-ATC <i>H</i> 
TE 50 <i>H</i> 	TE 50_02 <i>H</i> 	TE 50-AVR <i>H</i> 
TE 55 <i>H</i> 	TE 56 / TE 56-ATC <i>H</i> 	TE 60_02 <i>H</i> 
TE 60-ATC_02 <i>H</i> 	TE 60T <i>H</i> 	TE 60-ATC <i>H</i> 

TE 60T-ATC H 	TE 70 H 	TE 74 H
TE 75 H 	TE 76 / TE 76-ATC H 	TE 76P / TE 76P-ATC H
TE 80-ATC H 		

3.10 Breakers

TE 104 H 	TE 106 H 	TE 500 H
TE 500-AVR H 	TE 500-X H 	TE 504 H



TE 505 <i>H</i> 	TE 704 <i>H</i> 	TE 705 <i>H</i>
TE 706 / TE 706-AVR <i>H</i> 	TE 804 <i>H</i> 	TE 805 <i>H</i>
TE 905 / TE 905-AVR <i>H</i> 	TE 1000-AVR <i>H</i> 	TE 1500-AVR <i>H</i>

3.11 Mining tools

TE MD20 <i>R</i> 	TE-MW 80 No serial number tracking	TE-MW 130 No serial number tracking
-----------------------------	--	---

3.12 Direct fastening


DX 35 R 	DX 36M R 	DX E37 R
DX A40 R 	DX A41 R 	DX A41 I R
DXA 70R / DXA 70R-M R 	DX E72 R 	DX 76 / DX 76 PTR R
DX 350 R 	DX 351 / DX 351 BT / DX 351-CT R 	DX 450 R
DX 451 R 	DX 460 R 	DX 462 R

DX 600-N <i>R</i> 	DX 650 <i>R</i> 	DX 750 <i>R</i> 
DX 860-ENP / DX 860-HSN <i>R</i> 	GX 100 / GX 100-E <i>R</i> 	GX 120 / GX 120-ME <i>R</i> 
R4DW/R4DW-X-S / R4X12-S <i>R</i> 		

3.13 Testers

HAT 28 <i>R</i> 		
---	--	--

3.14 Angle grinders

AG 100-S <i>R</i> 	AG 125-S / AG 125-SE <i>R</i> 	AG 230-S <i>R</i> 
DAG 115-S / DAG 450-D <i>R</i> 	DAG 125-S / DAG 125-SE <i>R</i> 	DC 125-EX <i>R</i> 
DC 125-S / DC 500/-S <i>R</i> 	DC-EX  No serial number tracking	DC 180-S <i>R</i> 
DC 700-S <i>R</i> 	DC 230-S <i>R</i> 	DCG 125-S / DCG 500-S <i>R</i> 
DEG 125/-S/-D/-P / DEG 500/-D <i>R</i> 	DEG 150-D/-P / DEG 600/-D/-P <i>R</i> 	WS 180 <i>R</i> 

HG 500 <i>R</i> 	DC 230 I-S Serial no. under protection cover	DAG 451-S <i>R</i> 
DAG 700-P <i>R</i> 	DCG 230-DB <i>R</i> 	

3.15 Electrical cutting saws



DCH 180-SL <i>R</i> 	DCG 230 <i>R</i> 	DCH 300 <i>R</i> 
---	---	--

3.16 Gasoline cutting saws

DS FS <i>R</i> 	DS KC62 <i>R</i> 	DS KC80 <i>R</i> 
DSH S64 <i>R</i> 	DSH S80 <i>R</i> 	DSH S80-16 / DSH S80-40 <i>R</i> 

DSH 700 <i>R</i> 	DSH 900 <i>R</i> 	
---	--	--

3.17 Diamond saws

DS-TS5-E <i>R</i> 	DS WS10 / DS WS15 <i>R</i> 	DS TS20-E <i>R</i> 
DS TS22 <i>R</i> 	DS TS32 <i>R</i> 	DS WS10-E <i>R</i> 

3.18 Diamond Tools Light

DCM 1.5 <i>R</i> 	DD 80-E <i>R</i> 	DD 100 <i>R</i> 
---	--	--

DD 110-DI-W <i>R</i> 	DD 100-MEC <i>R</i> 	DD 120 <i>R</i>
DD 130 <i>R</i> 	DD 160-E <i>R</i> 	DD 200 <i>R</i>
DD-HD <i>R</i> 	DD 250-E <i>R</i> 	DD 300 <i>R</i>
DD 350 <i>R</i> 	DD 400-E <i>R</i> 	DD 500 <i>R</i>
DD 750-HY <i>R</i> 	DD -ST 80 <i>R</i> 	DD -ST 100 <i>R</i>

DD -ST 120 <i>R</i> 	DD -ST 130 <i>R</i> 	DD-ST EC 1 <i>R</i>  No serial number tracking
DD EC-1 <i>R</i> 	DD REC-1 <i>R</i> 	DD-SE19 <i>R</i> 
DD-SE20 <i>R</i> 	DD-VP4.5 <i>R</i> 	DD-VP7 <i>R</i> 
DD VP-U <i>R</i> 	DD-VPX <i>R</i> 	DG 150 <i>R</i> 
DPC 20 <i>R</i> 	DCH 180-SL <i>R</i> 	DCH 230 <i>R</i> 

DCH 300 <i>R</i> 		
--	--	--

3.19 Vacuum cleaners

HG 8.1230 ERS <i>R</i> 	TDA-VC 40 <i>R</i> 	TDA-VC 30 /60 <i>R</i> 
VCD 50 <i>R</i> 	VCU 40 <i>R</i> 	VCU 40-M <i>R</i> 
WVC 40-M <i>R</i> 	VC 20-U <i>R</i> 	VC 20-UM <i>R</i> 
VC 40-U <i>R</i> 	VC 40-UM <i>R</i> 	VC 60-U <i>R</i> 